
PUSH-IN WIRE CONNECTORS


□ PC2252	□ PC2253
□ PC2254	□ PC2255
□ PC2258	


Model


To be sold only with installation instructions Installation Instructions:

- 1. Turn off power before installing or removing connectors.
- 2. May use rigid solid and rigid stranded copper conductors.
- 3. Strip wires approximately 11 mm/0.43 inches.
- 4. Insert stripped conductors into the connector fully.
- 5. Test your connection through the slot with a voltage tester.
- 6. To correct or change, hold the wire to be removed and twist alternately left and right while pulling on the connector.









*600V Max. building wring; 1000V Max. signs or luminaires.

c UL US 8. Wire	1U0	*600 V	105°C	22-12 AWG, Sol. Cu
LISTED Wire	Conn.	Note: UL Listing is valid for Model PC2258 only.		
₹ 16 F 1	24 A	450 V	T85°C	0,5-2,5 mm ² , Rigid



Warranty limited solely to repair or replacement; no warranty of merchantability, fitness for a particular purpose or consequential damages





